

# Storm Damage Summary

## Laura

- Transmission Lines (138KV and 69KV) - 100%
- GIWW Transmission Tower crossings (138KV and 69KV) - 100%
- Distribution Line Segments - 493 of 545 (90%)
- Substations - 13 of 18 (72%)
- Switching Stations - All 3 (100%)

## Delta

- No additional Transmission Line Damages
- Distribution Line Segments - 332 of 545 (61%) Damaged
- Substations - 2 Received additional damage
- Switching Stations - 1 Received additional damage